

FORM NO. 51-61
MAY 1949

SECRET

CLASSIFICATION

25X1

CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

25X1

INTELLOFAX 25

COUNTRY Czechoslovakia

C 4364

DATE DISTR. 30 Nov. 1951

SUBJECT Chemical Production Plant in Zilina

NO. OF PAGES /

25X1

PLACE
ACQUIREDNO. OF ENCLS. 1 (3 pages)
(LISTED BELOW)

25X1

DATE OF INFO
ACQUIRED

25X1

25X1

SUPPLEMENT
REPORT NO.THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE
OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE ACT 50
U.S.C. 31 AND 32 AS AMENDED. ITS TRANSMISSION OR THE REVELATION
OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PRO-
HIBITED BY LAW. REPRODUCTION OF THIS FORM IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

25X1

25X1

1. Attached for your information is a blueprint of the Chemical Production Plants (Zavody pre chemicku vyrobu) National Corporation factory in Zilina, together with a partial English-language key. This plant employs about 700 workers in the production of artificial fertilizers, plexiglass and sulfuric acid. The plant director is Ing. Balaz; the executive director is Dr. Ing. Otakar Sira; leading plant chemists include Ing. Haviar and Mrs. Zilova.*

2. Please return by 28 December 1951.

25X1 Comment: the plant employed about 300 workers in March 1950. At that time the plant director was Dr. Ing. Otakar Sira. Ing. Balaz and Ing. Stary were chief plant engineers. The plant produced sulfuric acid, superphosphates, copper sulfate, bearing metals, various resins and plastics.

25X1

CLASSIFICATION

SECRET

25X1

STATE	NAVY	NSRB	DISTRIBUTION											
AIR			ORR	X										

25X1

Annex

- 2 -

Legend

25X1

1. Living quarters
2. Depot and "superphosphate" production
3. Maturing and disintegration department
4. Depot for raw phosphate
5. - 8. Not indicated by Source
9. Artificial fertilizer production
10. Kitchen
11. Production for gum (sic)
12. Electric workshop
13. Laboratory (preparation of plexiglass)
14. Fuel depot
15. Plexiglass production
16. Hall with 3 compressors
17. Garages
18. Gate and administration
19. New construction of large hall
20. Pebble storage
21. Depot of "vyprařkov"
22. Ovens
23. Oxygen production (Heerestof ovens)
24. ~~Not indicated by Source~~ ACID RESERVOIR

25X1

~~SECRET~~

25X1



- 2 -

25X1



- 25. Living quarters
- 26. Copper vitriol production
- 27. Tools depot
- 28. Work shop
- 29. - 31. Workers quarters

1 Enclosure (Original only)

~~SECRET~~

M = 1:10,000

